

Mean only · raw
Harmonics · raw
Mean only · filtered
Harmonics · filtered
(a) Raw and cycle-filtered error
Force RMSE (N)
10^{0}
10^{-1}
10^{-2}
10^{-3}
Freq.
Gimbal
Wind
Step
Gust
Flat plate
(b) Harmonic reconstruction
Freq.
Gimbal
Wind
Step
Gust
Flat plate
+0.3680 in Step
0.50
0.75
1.00
Wrench fidelity